PART-I PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of school/ Institution)

1	(a) Name of the school	MAJOR INDER SINGH PUBLIC SCHOOL MOTIFUR, EL SHAHLOT, DUT JALANDHAR
	(b) Level/Standand of School:-	Upto 10th Standard
,	© Whether School is affliated to C.B.S.E.or P.S.E.B. if affliated then affliation No.	CBSE (Affiliation No. 1631205)
2	Location	MOTIPUR, Tensil SHAHKOT DISTI. JALANDHAR
3	Plot Area	27 - famu
4	Plinth Area	Total Plinth Area 2100 FT.
5	Number of Storey	Guound Floor & 2st Floor
6	Year of construction of building.	2012
7	If the building has been constructed under the Supervision of the Qualified Engineer, the following details may be given.	STEMPLUSH GUPTH (MIESTRUCTURES)
		150, SHANTI PURA, LADO WALI ROAD (JAL)
a)	Name of the Engineer with Qualification	
b)	Address of the Engineer	<u></u>
c)	Detail of structural drawings used in the construction.	<u></u>
d)	Name & Address of Architect with qualification.	······································
8	Whether the building has been constructed for the purpose of	
a)	School	Schoo)
b)	Residential purpose and converted for use as a school.	
9	Material used for roofs	
a)	R.C.C. slabs	R.C.C Slabs
b)	R.S. Joists & Battens	<u></u>
	Wooden Joints & Battens. Material used for walls	
5 100	Mud mortar	Cement morter
37.0	Cement mortar	
	Plaster i) Lime mortar ii) Cement mortar	Cernet morter
	Flooring:-	Conglomerate
	Conglomerate	Leng (b. Medice
	Terrazo	. 1 4 1 3 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1
c)	Brick paving	
	A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows.	Detail drawing attached. It is also certified that those is no
	Whether fire safety certificate obtained from conceroned fire officer.	te pending in any Hon'ble court.

PART - II

SCHOOL BUILDING SAFETY CERTIFICATE

(TO BE FILLED BY THE S.D.E OF P.W.D. B&R DEPARTMENT)

me of the School: MAJOR INDER SINGH PUBLIC SCHOOL MOTIPUR. Teh. SHAHKOT. DISH. TALANDHAR		
This office Assistant Engineer/Junior Engineer visited the above mentioned School on13.14.12023 and have visually inspected it for its safety and find it fit for normal use as a school building.		
In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.		
3) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging of roofs etc. immediately inspection of the undersigned be arranged to check the stability and the safety of the building.		
This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (indicate year upto which it can be used) Ol-4-2023 to 31-3-2024 (Under Normal Correlland)		
Ref. No. 507 Dated 17-4-2023		
Dated 17-4-2023 Executive Engineer Construction Division No. 1, PWD B&R Br., Jalundhay Cant.		